Environmental Protection (Darling Range Bauxite Mining Proposals) Exemption Order 2023

Alcoa Monthly Report
Clause 10

August 2026

Alcoa

Monthly Reporting Dashboard – Page 1

Section 10
Monitoring Potential Drainage Incidents

Turbidity Data

Site	No. Active Monitors [1]
Huntly	42
Willowdale	4
Total	**46**

Drainage Incidents

Site	No. Events (Aug-26)[2]
Huntly	0
Willowdale	0
Total	**0**

[1] Refers only to monitors located in areas covered by the Exemption Order.
[2] Potential Events - Currently being investigated in accordance with section 6(2) of the Exemption Order to determine whether any of the events were mining related.

Section 2 – Clause 10 2(c) (i)
Production and Exploration Summary

Production (HUN and WDL)	Month (Aug-26)	YTD (CY)	Limit	Status
Production Tonnes Huntly	1.6	10.8		
Production Tonnes Willowdale	0.9	7.1		
Total Bauxite Production Tonnes	**2.5**	**17.9**	**38 MT**	

Exploration	Month (Aug-26)	YTD (CY)	Limit	Status
Total Exploration Holes	**0**	**42,330**	**105,000**	

Legend

- Within Limit
- Approaching Limit
- Above Limit

Section 3 Clause 10 2(c) (i) and Clause 10 2(c) (iii)
Activities Summary and Forecast

Area	August 2026			September 2026			October 2026		
	*Cleared	Stabilised	Seeded	*Clearing	Stabilised	Seeded	*Clearing	Stabilised	Seeded
Huntly									
Total HUN Mine Disturbance Footprint (ha)	**33**	**2.9**	**0**	**40.8**	**8.6**	**0**	**59**	**99.4**	**0**
Total WDL mine disturbance footprint (ha)	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**0**

Definitions

- Cleared – disturbance to native vegetation and other flora
- Stabilised– in relation to an area that has been disturbed, means carry out landscaping, ripping and other appropriate operations to prevent erosion of sediment, promote infiltration and manage surface water runoff
- Seeded – landform established and seeding complete

* Clearing only considers completed hectares

Monthly Reporting Dashboard – Page 2

Section 4 – Clause 2(c) (ii)
Activities Ceased during the Period for Huntly

Area	August 2026		
	Haul Roads [a]	Infrastructure [b]	Mining
Within 1km Reservoir (ha)	0	0	0
Serpentine Pipehead Dam Catchment (ha)	0	0	0
Within RPZ and >16% average slope (ha)	0	0	0
Within 10m of BC nesting/significant trees (ha)	0	0	0

Definitions

(a) Haul roads includes road infrastructure

(b) Infrastructure Includes drainage control, mining and monitoring infrastructure

Maps for Huntly


No cessation activities to report this month

Maps for Willowdale


Cessation of mining activities in the above-mentioned areas is not applicable to the Willowdale mine

Appendix A – Monitoring Results

Huntly




Willowdale



Appendix A – Monitoring Results

Exploration

No Exploration drilling activities to report this month



Clearing
Area Open
Mine Disturbance Footprint
Mt Solus 1.5km Buffer

Serpentine Pipehead Dam Catchment
Within 1km of Reservoir
Reservoir Protection Zones (RPZ)
Slope >16% (Landgate Derived)


Huntly

01-08-2026 to 31-08-2026

0 2.5 5 10
Kilometres

Alcoa

Date Exported: 2026-09-04



N

Clearing
Area Open
Mine Disturbance Footprint
Within 1km of Reservoir
Reservoir Protection Zones (RPZ)
Slope >16% (Landgate Derived)

Willowdale

01-08-2026 to 31-08-2026

0 1 2 4

Kilometres

Alcoa

Date Exported: 2026-09-04